



FIX AUTO POWAY

OPERATED BY CHROME COLLISION, INC.
13175 Gregg St., Poway, CA 92064
Phone: (858) 842-3075

Workfile ID: 533a9299
Federal ID: 27-3852846
State ID: 3326677
Resale Number: 102-093871
Federal EPA: N/A
State EPA: CAL000367754
License Number: BC-007164
BAR: ARD00267660

Preliminary Estimate

Customer: [REDACTED]

Written By: Jeff Borja

Insured: [REDACTED]
Type of Loss:
Point of Impact: 08 Left Qtr Post (Left Side)

Policy #:
Date of Loss:

Claim #:
Days to Repair: 0


Owner:
[REDACTED]
[REDACTED]
[REDACTED]
[REDACTED]

Inspection Location:
FIX AUTO POWAY
13175 Gregg St.
Poway, CA 92064
Repair Facility
(858) 842-3075 Business

Insurance Company:
CUSTOMER PAY

VEHICLE

2022 RIVI R1T Adventure Pkg AWD 4D P/U Electric- Electric gray



Interior Color:
Exterior Color: gray
Production Date: 12/2022

Mileage In:
Mileage Out:
Condition:
Vehicle Out:
Job #:

TRANSMISSION

Automatic Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Heated Mirrors
Power Driver Seat
Power Passenger Seat
Memory Package

DECOR

Dual Mirrors
Privacy Glass
Console/Storage
Wood Interior Trim

CONVENIENCE

Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Steering Wheel Touch Controls
Telescopic Wheel
Heated Steering Wheel
Climate Control
Dual Air Condition
Navigation System
Backup Camera
Parking Sensors
Surround View Camera
Remote Starter

RADIO

AM Radio

Stereo
Search/Seek
Auxiliary Audio Connection
Premium Radio

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Traction Control
Stability Control
Front Side Impact Air Bags
Head/Curtain Air Bags
Hands Free Device
Xenon or L.E.D. Headlamps
Blind Spot Detection
Lane Departure Warning

ROOF

Skyview Roof

Bucket Seats
Reclining/Lounge Seats
Leather Seats
Heated Seats
Ventilated Seats

WHEELS

20" Or Larger Wheels

PAINT

Clear Coat Paint

OTHER

Fog Lamps
Rear Spoiler
Signal Integrated Mirrors

TRUCK

Bedliner
Trailer Hitch
Power Trunk/Liftgate

Preliminary Estimate

Customer: XXXXXXXXXX

2022 RIVI R1T Adventure Pkg AWD 4D P/U Electric- Electric gray

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	#	***** NOTES *****		1			
2	#	** Customer Pay Estimate Requested **		1			
3	#	** Preliminary Estimate can change after Disassembly **		1			
		Note: TEARDOWN/DISASSEMBLY NECESSARY TO ASSESS THE EXTENT OF THE DAMAGE OR EVALUATE THE CONDITION OF THE VEHICLE AND/OR VEHICLE COMPONENTS IN ORDER TO ACCURATELY PREPARE REPAIR ESTIMATE					
4	#	** This vehicle is equipped with Cameras or Radar **		1			
5	#	** and requires calibration of ADAS Systems **		1			
6	#	** Which is not included in the estimate **		1			
7	HOOD						
8	R&I	Storage compart Note: for access to disconnect 12bv battery				1.0	
9	ELECTRICAL						
10	*	Rpr <u>Disconnect 12v Battery(s)</u> Note: LABOR: Time is after storage compartment is removed.			m	<u>0.2</u>	
11	Repl	High voltage system deactivate/activate Note: LABOR: Time is for deactivating and activating the high voltage power system as outlined in the OEM service manual. Time does not include D&R 12v battery.		1	m	2.8 M	
12	WINDSHIELD						
13	*	Rpr <u>Windshield MASK/ROPE</u>				<u>0.3</u>	
14	ROOF						
15	Repl	LT Roof molding Note: PARTS: Part cannot be reused/reinstalled.	PT00876020A	1	163.42	0.3	
16	PILLARS, ROCKER & FLOOR						
17	*	Blnd LT Aperture panel Note: PER OEM SERVICE MANUAL- Rivian does not approve of, condone, or recommend clear coat blending in any collision repair. Furthermore, Rivian strongly recommends that repairers use clear coat blending procedures only on interior structures that are minimally exposed to environmental elements. The preferred process approved by Rivian is to blend the base coat color as necessary to create a seamless transition. Next, apply clear coat to the entire panel using paint manufacturer recommendations. Clear coat should be applied to the entire panel, from edge to edge, or to a break point that allows for proper adhesion and material flow. A blended clear coated area is not robust, and over time the edges of the clear coated area will lift and discolor, making the repair area edge very noticeable. Because the thickness of the clear coat in a blended area thins at the edges, over a period the blended edges of the repair area will become visible.					<u>2.5</u>
18	R&I	LT Lwr ctr plr trim Note: for access to properly refinish and mask				0.5	
19	R&I	LT Lock pillar trim lower Note: for access to properly refinish and mask				0.2	
20	R&I	LT Front sill plate Note: for access to properly refinish and mask				Incl.	

Preliminary Estimate

Customer: XXXXXXXXXX

2022 RIVI R1T Adventure Pkg AWD 4D P/U Electric- Electric gray

Note: a diagnostic and repair interface available on the vehicle touchscreen to help both internal and third-party technicians service vehicles more efficiently

55	#	Keep HV battery maintained to a safe level	1		0.5
56	#	Calibrate camera	1		
Note: Price per invoice					
57	MISCELLANEOUS OPERATIONS				
58	#	Repl Cover / mask entire exterior of vehicle to prevent overspray	1	10.00	0.2
59	#	Cover / mask for prime and block	1	2.50	0.1
60	#	Cover / mask recessed edges / jams / weatherstrips	1	2.50	0.2
61	#	Cover electrical connectors and plugs for contamination	1	2.50	0.1
62	#	Tint to achieve color match	1		0.5
63	#	Corrosion Protection	1	10.00	
64	#	Feather Prime and Block	1		0.5
65	#	De-Nib & Finesse	1		0.5
66		OTHER CHARGES			
67	#	E.P.C.	1	5.00	
SUBTOTALS				554.08	20.1
					6.9

NOTES

Prior Damage Notes:
none

ESTIMATE TOTALS

Category	Basis	Rate	Cost \$
Parts			549.08
Body Labor	15.8 hrs @	\$ 95.00 /hr	1,501.00
Paint Labor	6.9 hrs @	\$ 95.00 /hr	655.50
Mechanical Labor	4.3 hrs @	\$ 250.00 /hr	1,075.00
Paint Supplies	6.9 hrs @	\$ 65.00 /hr	448.50
Body Supplies	16.9 hrs @	\$ 2.00 /hr	33.80
Other Charges			5.00
Subtotal			4,267.88
Sales Tax	\$ 1,031.38 @	7.7500 %	79.93
Grand Total			4,347.81